

MILESTONE INSPECTION REPORT FORMS - STRUCTURAL BSIP INSPECTION FORM

Form EB18 – 2024

MILESTONE INSPECTION REPORT FORM

PHASE 1 Milestone Inspection

Initial Phase 1 Inspection Report Amended Phase 1 Inspection Report as required after completion of any repairs.

Note: All Required Fields Appear in Red

Licensed Engineer(s) or Architect(s) Responsible for the Milestone Inspection

Inspection Firm Name (if applicable): Kimley-Horn and Associates, Inc.

Inspection Engineer/Architect Name and License Number: Sheila Preble, PE 91024

Address: 1920 Wekiva Way, Suite 200, West Palm Beach FL, 33411

Telephone Number: 561-840-0281

Assuming Responsibility for: All Portion - If Portion please list: _____

Inspection Commenced Date: 10/03/2024 Inspection Completed Date: 10/03/2024

Additional Inspection Firm Name (if applicable): _____

Additional Inspection Engineer/Architect Name: _____

Address: _____

Telephone Number: _____

Assuming responsibility for: All Portion – If portion please list: _____

Inspection Commenced Date: _____ Inspection Completed Date: _____

NOTE: Add pages as required to list all additional design professionals assuming responsibility for the Milestone Inspection or portions thereof. Each Design Professional must sign and seal their portion of the work in accordance with Florida Statutes.

Please check all that apply:

Substantial Structural Deterioration Observed; Phase 2 inspection is required

Reason to Believe a Dangerous Inaccessible Condition of Major Structural Component; Phase 2 inspection is required to complete Milestone Inspection of Inaccessible Conditions

Dangerous Condition Observed; Structural Evaluation is required; A Phase 2 Inspection is required

**A condition exists that the Milestone Inspector determines would need a Phase 2 Inspection or structural evaluation of the specific item identified or area in order to determine whether a dangerous condition exists.*

Immediate Dangerous Condition Observed; Notify Building and Fire Official; Structural Evaluation May be required, possible Shoring and a Phase 2 inspection is required

Maintenance Needed but does not raise to the level of Substantial Deterioration or Dangerous. Phase 1 Inspection Passes

Passed Phase 1 Inspections


Licensed Design Professional:

Engineer


Architect

Name: Sheila Preble

License Number: 91024



Seal



Click the button below to check if all required fields are completed.
If they are not, you will be told which fields must be completed.
If they are, the signature box below will unlock, allowing you to sign and lock the form.

Check Required Fields

This item has been digitally signed and sealed by Sheila Preble on date adjacent to seal. Printed copies of this document are not considered signed and sealed and the signature must be verified on electronic copies.

I am qualified to practice in the discipline in which I am hereby signing,

Signature:  Date 12/10/2024

This report has been based upon the minimum milestone inspection requirements as listed in *Chapter 18 of the Florida Building Code, Existing Building*. To the best of my knowledge and ability, this report represents an accurate appraisal of the present condition of the structure, based upon careful evaluation of observed conditions, to the extent reasonably possible.

See: General Considerations & Guideline

Supporting Data Attached:

Add Attachments

- APPENDIX A- AERIAL VIEW
- APPENDIX B- REFERENCE PHOTOGRAPHS